



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

May 2, 2008

Supervisor

<b>Mine Name:</b> Mossy Rock Mine	<b>Permit Number:</b> S/039/0025
<b>Operator Name:</b> Meyer Construction Inc.	<b>Inspection Date:</b> April 30, 2008
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 1:40 pm
<b>Other Participants:</b> None	<b>Mine Status:</b> Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

The gate on the road leading to this site was locked, prohibiting vehicle access. It appears that this site has not been active since last fall when it was shut down until the operator provided a Notice of Intent and posted a reclamation surety. The Notice was submitted and found to be complete, however the operator has yet to post the surety.

#### Conclusions and Recommendations:

Since the operator is apparently complying with the Division's order to cease operations until the site is properly permitted and bonded, No enforcement action is warranted at this time. I spoke with the operator about a week ago – he is trying to arrange for the surety.

Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

cc: John Meyer, Meyer Construction Inc.

O:\M039-Sanpete\S0390025-MossyRock\inspections\Insp-04302008-mossyrock.doc

080001